RAE Engineering and Inspection Ltd.

#111,4808'- 87 Street, Edmonton, Alberta T6E 5W3 Phone: (780) 469-2401 Fax (780) 468-2422

Field Inspection Report

Vessel # 228209

Client	Canadian Natural Resources Ltd.		Inspect	ion Date	2003-06-23		18-			
Prov. Reg.#	228209		Insp. Ty	/pe	VE/VI/UT		-			
Equipment	Treater			Locatio	n	East Watts				
Tag/Equip. #				LSD		4-9-31-16W4				
Vessel Status	In Service		Comp./	Unit						
Manufacturer	Natco	Serial #		L8227		MAW	/P/Temp	345	kPa	93 C
CRN#	F5837.2	Shell Ma	aterial	SA-516-7	70	Shell	Thick.		7.900	mm
Corrosion All.	mm	Head Material		SA-516-7	70	Head Thick.		9.500 mm		
Manway	Yes	Head Material 2				Head	Thick. 2			mm
Coating	No	Channe	Material	Channel Thick		nel Thick.			mm	
Diameter	2438 mm	Length	7625 mm	Height	mm	RT		нт		
Year Built	1985	Next Ins	pection	2005		Next	Insp. Typı	NA		
Service	Sweet					Job # 03-268				

PSV #.	29995A10					
Mfg.	Farris	Serial #	29995A10	Set Pressure	345	kPa
Type/Model		Capacity	44 M³/Min	Size	76.200	mm
Date of Service	2003-06-01	Next Service	2007	Service Co.		

Observations:

External

Coating still in serviceable condition. No active external corrosion. All valves, level glasses, gauges and controllers appear to be in good working order. Vessel inside - mounted on rail. The external part is fully insulated. The insulation is in good serviceable condition. PSV discharge is sufficient.

Date Printed

2003/06/30

RAE Engineering and Inspection Ltd.

#111,4808 - 87 Street, Edmonton, Alberta T6E 5W3 Phone: (780) 469-2401 Fax (780) 468-2422

Field Inspection Report

Vessel # 228209

Internal

West Side (firetubes). The interior was steam cleaned. Previous patch repairs on bottom of vessel still intact, no blisters or cracking evident. All internals intact and in good condition. Weir was found to be in good condition. No cracking on welds. The anodes were 30% consumed and replaced.

East Side - Delaminating and blistering of patch repairs evident. No open surface on metal. The internal was found to be in good condition - free of any active corrosion. All flanges in good condition.

Firetubes - UT wall thickness readings were taken and no significant metal loss could be detected. MPI was done on circular welds. No cracking evident. Slight isolated pit marks noted on both firetubes, less than 0.6 mm deep. The firetubes were found to be fit for service.

UT Measurements in mm Shell - 8.6 - 8.7 Head - 9.9 - 10.2

Recommendations:

- 1. Touch paint up on external piping.
- 2. Monitor patch repairs on internal coating yearly.
- 3. Fit for service.

Inspector: Hannes Roberts

Reviewed by:

☐ AB-40 to be attached

Report # 27405

Date Printed

2003/06/30

. RAE Inspection Service (1979) Ltd. #111, 4808 - 87 Street, Edmonton, Alberta T6E SW3

Phone: (780) 469-2401 Fax: (780) 468-2422

Vessel Drawing (not to scale)

Client	CNRL		Location		
Prov. Reg.#	228209		LSD	4-9-31-16W4	-
Equipment	Treater				
Diameter		Shell Material	SA-516-70	Shell Thickness	7.9 mm
Length/Height		Head Material	SA-516-70	Head Thickness	9.5 mm

FIRETUBE

			Ь
7		1	
6		2	
5	4	3	

LEFT	RIGHT
1. 9.3 TO 9.6	9.4 TO 9.6
2. 9.4 TO 9.5	9.3 TO 9.7
3. 9.3 TO 9.7	9.7 TO 9.8
4. 9.2 TO 9.4	9.7 TO 9.9
5. 9.4 TO 9.6	9.6 TO 9.4
6. 9.4 TO 9.7	9.6 TO 9.7
7. 9.5 TO 9.7	9.3 TO 9.5