

Please submit to: 9410 – 20th Avenue Edmonton, AB T6N 0A4 Tel (780) 437-9100 Fax (780) 437-7787 E-Mail: Records@absa.ca AB-10 2012-12

BOILER AND PRESSURE VESSEL STATUS REPORT

NOTE: This form may be used to provide notification of changes in ownership, location, operating status or scrapped boilers and pressure vessels.

Please review the responsibilities of the vendor and the new owner under Section 36 of the Pressure Equipment Safety Regulation. (regulation can be found on our website www.absa.ca)

Safety Regulat	tion. (r	egulation can be t	ound on our v	vebsite www.absa.ca	a)	
Re: Vessel (A)	1)	A0487741	2)		3)	
Serial No.		VS-11687				
CRN	-	B3524.21				
Vessel(s) sold Name of Nev	_			gistration of the vess CANADA LTD	sel(s) to:	
Mailing	Addre	ss:				
New Location o	f Vess	sel:				
				(Street Address		
Contact Perso			<u> </u>		Tel:	
E-M Date of Sa		-			PO No.:	
Vessel(s) remo	ved fi	om service on:	<u> </u>			
	espon		the vessel is i	nspected by ABSA p	prior to it being returned to service in the	
The above vess	sel(s) ı	returned to servi	ce on:			
Inspected on:	_			(Date).	Inspection Report attached	
Vessel(s) reloc	ated t	o:				
	(Street Address <u>or</u> LSD)					
the applicable a	nnual	fee(s) will remain	in force to you	ur account. Respons	will record the location as unknown, and sibility for safe operation in Albertan, you are required to notify ABSA.	
We sold this very owner. Response are received by	sibility	for safe operation	ow to whom . in Alberta als	(ABSA records will i o remains with your	retain your company name as the company until new ownership details	
		•	ovince of Alb	erta since	(Date). Please	
remove from annual registration. You are required to notify ABSA if the vessel returns to service in Alberta.						
Vessel Scrappe	d – <i>F</i>	All three condi	tions belov	v must be satis	fied	
☐ Vessel has been removed from service and there is no intention to return it to pressure service.						
☐ The nameplate has been removed and all other identification has been removed.						
		ition that it cannot ad has been cut o		ed. i.e. A hole has be	een cut in the vessel, or a nozzle has	
Company Name:	Company Name: Canadian Natural Resources Limited.					
Position Title:	Ass	ets Integrity Anlay	/st	_ Tel: _587-955-02	58	
(Please print name):	JAS	SMINE LE	- , ,,	E-mail: JASMINE	E.LE@CNRL.COM	
Signature:		h		Date; JAN 07/20	19	