

A0446638 - SEPARATOR INSPECTION - NOV 1998

1060-04

Canadian Natural Resources Limited  
Production - Facilities Engineering  
A0446638 Horizontal Separator Certificate of Inspection

Content Date Range: 11/19/1998 to 11/19/1998

Vessel Integrity

Inspection Data

Open: 1/31/2007 Close:

CC+2 OP P

Vial: Yes  
Original: Yes  
Confidential: No



00761974



VESSEL (A): 0446638

DATE OF INSPECTION: 1998 Nov 19



DEC 09 1998

# Certificate of Inspection

BERKLEY PETROLEUM CORP.  
1250, 202 - 6 AVENUE SW

CALGARY, AB  
T2P 2R9

PREFERRED RE-INSP. INTERVAL: 2.00 Yr.  
CRN: L3845.21

YEAR BUILT: 1998  
VOLUME: 2.37 M3

HEATING SURFACE:  
SURFACE AREA:  
COMPANY CODE:

LOCATION: 1250, 202 - 6 AVENUE S.W., CALGARY

DESCRIPTION: HORIZONTAL SEPARATOR

MANUFACTURER: RUSHTON GAS & OIL

SERIAL #: C848A.HS

### Safety Valves

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	VALVE ID	SETTING	CAPACITY	LOCATION
SEP	9929 KPA	54 C	-29 C	SV1			TO BE INSTALLED

### OWNER INSTRUCTIONS/REMARKS:

CONTACT THE ABSA SAFETY CODES OFFICER BEFORE PLACING THE VESSEL/BOILER IN SERVICE.

VESSEL/BOILER TO BE INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT AND REGULATIONS.

VERIFY THAT VESSEL/BOILER IS PROTECTED BY A CODE PRESSURE RELIEF VALVE, OF ADEQUATE CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED AND INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT & REGULATIONS.

Safety Codes Officer: LAKE, HAROLD

Signature:

### NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.